


450 FBL Head Kit



All Screws should be fix with Loctide.
 Thrust bearings need apply grease.